

## Message Text

UNCLASSIFIED

PAGE 01 STATE 304208  
ORIGIN SNM-05

INFO OCT-01 ARA-14 ISO-00 AID-05 /025 R

DRAFTED BY S/NM:RHALL:LCR  
APPROVED BY S/NM:JLINNEMANN  
AID/SER/INC:MEWAMPLER (INFO)  
ARA/LA/NC:DCOX (INFO)  
-----119853 220654Z /16

R 212210Z DEC 77  
FM SECSTATE WASHDC  
TO AMEMBASSY BOGOTA

UNCLAS STATE 304208

E.O. 11652: N/A

TAGS: SNAR

SUBJECT: TQ-05 AIRCRAFT ENGINE REPAIR

REF: BOGOTA 11597

1. ROCKWELL ADVISES THAT EXTENSIVE COWL MODS REQUIRED TO ACCEPT TURBO 540 ENGINES.
2. DOLLARS 15,988 MANUFACTURER SUGGESTED PRICE FOR RE-MANUFACTURED, EXCHANGE ENGINE.
3. MANN AIRCRAFT CO. MIAMI, FLA., A LICENSED FACTORY DEALER QUOTES FOR IGO 540-AIA (AIC-BIA-BIC) DOLLARS 15,988 LESS 15 PER CENT DISCOUNT FOR HELI-COL WITH LEAD TIME OF 12-14 WEEKS.
4. RECOMMEND OPTION A REFTTEL OR NEW OPTION D. (SLING AIRCRAFT WITH 212 TO EITHER BARRANQUILLA OR NEAREST MAINTENANCE FACILITY. VANCE

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 STATE 304208

UNCLASSIFIED

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01-Jan-1994 12:00:00 am  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** AIRCRAFT MAINTENANCE, ENGINES  
**Control Number:** n/a  
**Copy:** SINGLE  
**Sent Date:** 21-Dec-1977 12:00:00 am  
**Decaption Date:** 01-Jan-1960 12:00:00 am  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01-Jan-1960 12:00:00 am  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1977STATE304208  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** RHALL:LCR  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Expiration:**  
**Film Number:** D770477-0177  
**Format:** TEL  
**From:** STATE  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1977/newtext/t19771230/aaaaayxm.tel  
**Line Count:** 55  
**Litigation Code IDs:**  
**Litigation Codes:**  
**Litigation History:**  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Message ID:** 191b16ff-c188-dd11-92da-001cc4696bcc  
**Office:** ORIGIN SNM  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 2  
**Previous Channel Indicators:** n/a  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** 77 BOGOTA 11597  
**Retention:** 0  
**Review Action:** RELEASED, APPROVED  
**Review Content Flags:**  
**Review Date:** 29-Mar-2005 12:00:00 am  
**Review Event:**  
**Review Exemptions:** n/a  
**Review Media Identifier:**  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**SAS ID:** 155792  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** TQ-05 AIRCRAFT ENGINE REPAIR  
**TAGS:** SNAR, EAIR, CO  
**To:** BOGOTA  
**Type:** TE  
**vdkgvwkey:** odbc://SAS/SAS.dbo.SAS\_Docs/191b16ff-c188-dd11-92da-001cc4696bcc  
**Review Markings:**  
Margaret P. Grafeld  
Declassified/Released  
US Department of State  
EO Systematic Review  
22 May 2009  
**Markings:** Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 22 May 2009